

# **IMPORTANT SAFETY NOTICE**

**BAJA MOTORSPORTS IS VOLUNTARILY RECALLING  
MINI BIKE MODELS BEGINNING WITH HT65, MB165, WR65,  
MB196, DB30, DR90 AND WR90  
GO-CART MODELS BB65, SD65, DN65 AND TR65**

**Sold 2004 through 2010**



**Replacement Gas Cap (All Listed Models)**

**Install throttle cable clamp and replace the existing fuel line  
(Mini Bike Models WR65, MB165, MB196 and HT65)**

**Consumers should immediately stop using the above referenced products and contact Baja Motorsports to obtain free repair kits and/or schedule repairs at an authorized service center at no charge to you.**

**If you have any questions or require additional information, or to locate an authorized service center, please contact BAJA Motorsports Customer Service at **1-888-863-2252** or visit [www.bajamotorsports.com](http://www.bajamotorsports.com)**

**In cooperation with the  
U. S. Consumer Product Safety Commission**

**Post for 120 days or until at least November 12, 2010**